

# NOTICE TO MARINERS

## GIPPSLAND PORTS



The following navigation notice is published for general information.

**AUSTRALIA - VICTORIA**

**NOTICE TO MARINERS No.232 OF 2024**

**PORT OF CORNER INLET AND PORT ALBERT**

**MAJOR BUOY EXCHANGE COMPLETED**

**DATE:** Thursday 30<sup>th</sup> May 2024

**PREVIOUS NOTICE:** Local Navigation Notice No.3(P) of 2024 is referred and cancelled.

**DETAILS:** Mariners are advised that the Port of Corner Inlet and Port Albert 2024 Major Buoy Exchange has been completed.

There has been a change to the position of two Major Buoys as follows:

1/ Port Albert Entrance Fairway Buoy (LFl.10s) has been repositioned approximately 20m West and established in position;

Lat. 38° 45.302' South  
Lon. 146° 42.385' East

2/ Corner Inlet No.4 Port Lateral Mark Buoy (Fl.R.4s) has been repositioned approximately 70m South East and established in position;

Lat. 38° 48.097' South  
Lon. 146° 30.095' East

There is no change to the position or flash character of the other 3 buoys exchanged.

- Port Albert Entrance Outer Starboard Lateral Mark Buoy (Fl.G.3s)
- Corner Inlet Entrance No.5 Starboard Lateral Mark Buoy (Fl.G.3s)
- Corner Inlet No.6 Port Lateral Mark Buoy (Fl.R.4s)

Further details can be obtained from Gippsland Ports Harbour Master on 0427 610 025

# NOTICE TO MARINERS

## GIPPSLAND PORTS



**CHARTS**

**AFFECTED:** Chart Aus.181 – ENC AU439146

**PUBLICATIONS**

**AFFECTED:** Gippsland Ports Waterways Online available at;  
[Gippsland Ports - Waterways Online v2 \(arcgis.com\)](http://arcgis.com)

**FURTHER**

**NOTICE:** No Further Notice will be issued.

**CAPT. BEVIS HAYWARD**  
**HARBOUR MASTER**  
**GIPPSLAND PORTS**