

# NOTICE TO MARINERS

## GIPPSLAND PORTS



The following navigation notice is published for general information.

**AUSTRALIA - VICTORIA**

**NOTICE TO MARINERS No.357 OF 2024**

**PORT OF CORNER INLET AND PORT ALBERT**

**TOORA CHANNEL**

**No.6 PORT LATERAL LIGHT BEACON COMPROMISED**

**DATE:** Thursday 29<sup>th</sup> August 2024

**PREVIOUS NOTICE:** No previous Notice Issued

**DETAILS:** Mariners are advised that the Toora Channel No.6 Port Lateral Mark Beacon (Fl.R.4s) has been compromised during a recent severe weather event and is missing off station.  
The former position of Toora No.6 Beacon;  
Lat. 38° 43.863' S  
Lon. 146° 22.808' E  
A temporary Port Lateral Buoy with the same Flash Character will be established when environmental conditions permit and following a sounding of the area to establish the position of the beacon on the sea floor.  
Toora No.6 Beacon is replicated on high resolution ECDIS ENC Cell Au5BAR01

**CHART AFFECTED:** Aus 181 & ENC Cell Au439146 & ENC Cell Au5BAR01

**PUBLICATIONS AFFECTED:** Gippsland Ports Waterways Online at;  
[Gippsland Ports - Waterways Online v2 \(arctis.com\)](https://www.gippslandports.com.au/waterways-online)

**FURTHER NOTICE:** A Further Notice will be issued.

**CAPT. BEVIS HAYWARD  
HARBOUR MASTER  
GIPPSLAND PORTS**