

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

LNN No.2 OF 2025

PORT OF ANDERSON INLET

ANDERSON INLET CHANNEL - BUOY EXCHANGE COMPLETED

DATE:	Monday 28 th April 2025
PREVIOUS NOTICE:	No previous Notice issued.
DETAILS:	<p>Mariners are advised that the Anderson Inlet Channel buoy exchange program has been completed. The exchange included channel realignment and relocation of 4 Unlit Nav Aid Buoys as follows;</p> <p>Anderson Inlet No.7 Starboard Lateral Mark Buoy relocated to new position; Lat. 38° 38.654' S Lon. 145° 47.527' E</p> <p>Anderson Inlet No.24 Port Lateral Mark Buoy relocated to new position; Lat. 38° 38.441' S Lon. 145° 47.516' E</p> <p>Anderson Inlet No.26 Port Lateral Mark Buoy relocated to new position; Lat. 38° 38.907' S Lon. 145° 47.623' E</p> <p>Anderson Inlet No.30 Port Lateral Mark Buoy relocated to new position; Lat. 38° 39.255' S Lon. 145° 47.204' E</p> <p>Channel configuration and alignment can be viewed on Gippsland Ports Waterways Online Mapping @ Gippsland Ports - Waterways Online v2</p>
CHART AND ENC AFFECTED:	N/A
PUBLICATIONS AFFECTED:	Gippsland Ports Waterways Online available at; Gippsland Ports - Waterways Online v2
FURTHER NOTICE:	No Further Notice shall be issued

**BEVIS HAYWARD
HARBOUR MASTER
GIPPSLAND PORTS**