

LOCAL NAVIGATION NOTICE

GIPPSLAND PORTS



The following navigation warning is published for general information.

AUSTRALIA – VICTORIA

Local Navigation Notice No.3 of 2025

PORT OF GIPPSLAND LAKES

LAKE VICTORIA – ISOLATED DANGER BUOY WITHDRAWN FROM SERVICE

DATE: 22nd May 2025

DETAILS: Mariners are advised that the mud island which appeared in the waters of Lake Victoria, adjacent to the township of Loch Sport, approximately 700m Northwest of Seagull Drive Boat ramp has disappeared.

The Isolated Danger Buoy (FLW 2s) marking the location of the island has been withdrawn from the location:

Lat. 38° 01.920' South

Lon. 147° 35.268' East

Datum WGS84

Mariners are reminded to navigate in the fairway, well to the north of the Port hand Lateral marks, especially at night and to take particular care when navigating through Lake Victoria as it is unpredictable where or when any further islands could appear.

Please contact Gippsland Ports on (03) 51 500 500 to report navigation hazards.

PUBLICATIONS Gippsland Ports Waterways Online website at
AFFECTED: <https://www.gippslandports.vic.gov.au/boating/waterways-online/>

PREVIOUS LNW No.14 of 2022 - Port of Gippsland Lakes - Lake Victoria - Mud Island
NOTICE: Loch Sport has been cancelled.

FURTHER No further notice will be issued.
NOTICE:

DAVID ASHWORTH
ASSISTANT HARBOUR MASTER