

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No.368 OF 2025

PORT OF GIPPSLAND LAKES

REEVE CHANNEL

STARBOARD LATERAL MARK BUOY No.1A

WITHDRAWN FROM SERVICE

DATE: 16th July 2025

PREVIOUS NOTICE: Notice to Mariners No.152(T) of 2020 is referred.

DETAILS: Mariners are advised that the Reeve Channel Starboard Lateral Mark No.1A Buoy (Fl.G.3s), formerly in position:
Lat. 37° 52.806' S
Lon. 147° 57.563' E
has been permanently withdrawn from service.

For further information please call Gippsland Ports Harbour Master on 0427 610 025

**CHARTS
AFFECTED:** ENC Cell AUSLEN01

**PUBLICATIONS
AFFECTED:** Gippsland Ports Waterways online website available at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER
NOTICE:** No further Notice will be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER
GIPPSLAND PORTS**