

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation warning is published for general information

AUSTRALIA - VICTORIA

No.546 OF 2025

PORT OF ANDERSON INLET

ANDERSON INLET ENTRANCE - SAFE WATER MARK BUOY

POSITION CHANGED

DATE: 7th November 2025

DETAILS: Mariners are advised that the position of the Anderson Inlet Entrance Offshore Safe Water Mark Buoy (L.FI.10s) has changed. The new position of the Buoy is as follows.
Lat. 38° 39.408' South
Lon. 145° 43.305' East Datum WGS84

Mariners are reminded that the Safe Water Mark Buoy does not indicate any navigation significance other than being a reference point in deeper water.

Mariners are also advised that the recent survey of the entrance does not indicate any safe fairway across the Anderson Inlet Bar.

**CHARTS
AFFECTED:** ENC Cell 439145

**PUBLICATIONS
AFFECTED:** Gippsland Ports Waterways online website available at;
<https://www.gippslandports.vic.gov.au/boating/waterways-online/>

**FURTHER
NOTICE:** No further notice will be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER
GIPPSLAND PORTS**