

NOTICE TO MARINERS

GIPPSLAND PORTS



The following navigation notice is published for general information.

AUSTRALIA - VICTORIA

NOTICE TO MARINERS No.142 OF 2025

PORT OF CORNER INLET AND PORT ALBERT

CORNER INLET ENTRANCE CHANNEL

No.3 AND No.5 STARBOARD LATERAL MARK BUOYS

SYNTHETIC AIS AID TO NAVIGATION ESTABLISHED

DATE: Tuesday 11th March 2025

PREVIOUS NOTICE: No previous Notice issued

DETAILS: Mariners are advised that Synthetic AIS Aids to Navigation have been established for the following Corner Inlet Entrance Channel Buoys;
No.3 Starboard Lateral Mark Buoy (Q.G.)
Lat. 38° 51.086' South
Lon. 146° 34.105' East
No.5 Starboard Lateral Mark Buoy (Fl.G.3s)
Lat. 38° 50.593' South
Lon. 146° 33.408' East

The No.3 AIS Aid to Navigation is named "Corner Inlet Entrance No.3" with the AIS MMSI number 995036313.

The No.5 AIS Aid to Navigation is named "Corner Inlet Entrance No.5" With the AIS MMSI number 995036314

CHART AFFECTED: Chart Aus.181- ENC Cell 439146

PUBLICATIONS AFFECTED: Nil.

FURTHER NOTICE: No further Notice will be issued.

**CAPT. BEVIS HAYWARD
HARBOUR MASTER
GIPPSLAND PORTS**